



Aceite hidráulico NO incluido



Este logsplitter de Troy-Bilt se envía sin el líquido hidráulico en su depósito. Es la responsabilidad del cliente comprar y agregar el líquido hidráulico antes de encender el motor de los logsplitter y/o de funcionar el logsplitter. Encender el motor sin el volumen apropiado de un líquido hidráulico aprobado en el depósito dará lugar a la falta catastrófica de la pompa hidráulica. Los líquidos aprobados en la fábrica se enumeran abajo.

- Dexron®-III/de Mecron® Líquido de la transmisión automática*
- Aceite hidráulico de 10-Weight AW
- Pro-Mix® AW-32 aceite hidráulico

Referir al manual del operador de tu divisor del registro para la información adicional con respecto a capacidades del depósito, llenando el depósito y comprobando el nivel fluido hidráulico. Leer el manual del operador entero antes de funcionar el divisor del registro.

Hydraulic oil NOT included



This Troy-Bilt logsplitter is shipped without hydraulic fluid in its reservoir. It is the responsibility of the customer to purchase and add hydraulic fluid before starting the logsplitter's engine and/or operating the logsplitter. Starting the engine without the proper volume of an approved hydraulic fluid in the reservoir will result in catastrophic failure of the hydraulic pump. Factory-approved fluids are listed below.

- Dexron®-III / Mecron® Automatic Transmission Fluid*
- 10-Weight AW hydraulic oil
- Pro-Mix® AW-32 hydraulic oil

Refer to your logsplitter's Operator's Manual for additional information regarding reservoir capacities, filling the reservoir and checking hydraulic fluid level. Read the entire Operator's Manual prior to operating the logsplitter.

*Dexron® es una marca registrada de la Corporación de General Motors.

*Mecron® es una marca registrada de Ford Motors Company

*Dexron® is a registered trademark of General Motors Corporation.

*Mecron® is a registered trademark of Ford Motors Company