



## Hydraulic oil NOT included



This *Troy-Bilt* logsplitter is shipped *without* hydraulic fluid in its reservoir. It is the responsibility of the customer to purchase and add hydraulic fluid *before* starting the logsplitter's engine and/or operating the logsplitter. Starting the engine without the proper volume of an approved hydraulic fluid in the reservoir will result in catastrophic failure of the hydraulic pump. Factory-approved fluids are listed below.

- Dexron®-III / Mecron® Automatic Transmission Fluid\*
- 10-Weight AW hydraulic oil
- Pro-Mix® AW-32 hydraulic oil

Refer to your logsplitter's Operator's Manual for additional information regarding reservoir capacities, filling the reservoir and checking hydraulic fluid level. Read the entire Operator's Manual prior to operating the logsplitter.

\*Dexron® is a registered trademark of General Motors Corporation.

\*Mecron® is a registered trademark of Ford Motors Company